



# Impacts by Vehicle

Date: 10/16/2002

Time: 1:30 PM

Page: 2

<b>Vehicle Auth.</b>	<b>Vehicle</b>				
Impact Date	Impact Time	Operator Name	Impact Type	Threshold	Description
<i>Supervisor</i>					
<b>14 Crown Stock Picker #36</b>					
09/21/2001	9:25:12 PM	Quincy Smith	Hard	0.8	Hit beam over door when going from Warehouse A to Warehouse B while driving truck with hydraulics up. Mast of truck bent and truck out of service.
<i>Ross McBain</i>					
09/24/2001	4:04:47 AM	Mitchell Brown	Hard	0.8	Ran into rack in aisle #2. Rack bent and delared unsafe until welded. Product removed from racking until rack welded.
<i>Don Sabey</i>					
09/24/2001	6:17:16 AM	Mitchell Brown	Hard	0.8	Exited trailer too fast over dock plates. Dangerous driver warned to slow down as this is a safety haszard. No apparent damage to truck.
<i>Don Sabey</i>					
<b>12 Hyster Counterbalance #37</b>					
09/21/2001	9:23:20 PM	Andy Black	Hard	0.8	Backed into post and dented back of reach truck cab. Driver reprimanded and will be given additional training.
<i>Ralph Young</i>					
09/24/2001	4:04:03 AM	Todd McDowell	Hard	0.8	Damaged hydraulics and bent racking in aisle #3. Truck required to go to maintenance for repair.
<i>Don Sabey</i>					
09/25/2001	1:41:54 AM	Todd McDowell	Soft	0.3	Damaged hydraulics and bent racking in aisle #4. Truck required to go to maintenance for repair.
<i>Ian Johnson</i>					
<b>11 Raymond Pallet Jack #12</b>					
09/10/2001	10:16:21 AM	Don Jackson	Soft	0.7	New operator. Ran into unit #12 and bent forks. Driver sent for more training.
<i>Andy McTavish</i>					
09/11/2001	11:45:53 AM	Don Jackson	Hard	1.1	Exited trailer too fast and alarm set off when going over dock plates. Driver warned to slow down as this is a safety hazard. No apparent damages to jack
<i>Andy McTavish</i>					
09/24/2001	4:04:27 AM	John Jones	Hard	0.8	Hit the wall at end of warehouse while backing into charging area. No apparent damage.
<i>Don Sabey</i>					

# Impacts by Vehicle

Date: 10/16/2002

Time: 1:30 PM

Page: 3

<b>Vehicle Auth.</b>	<b>Vehicle</b>	<b>Impact Date</b>	<b>Impact Time</b>	<b>Operator Name</b>	<b>Impact Type</b>	<b>Threshold</b>	<b>Description</b>
<i>Supervisor</i>							
<b>13</b>	<b>Raymond Reach Truck #25</b>						
<i>Ralph Young</i>		09/21/2001	4:36:16 PM	Craig Morrow	Soft	0.3	Turned corner too fast and dumped shrink wrapped pallet of product. Product written off as damage was extensive. Cost of destroyed product \$980.00. Driver warned to slow down.
<i>Don Sabey</i>		09/24/2001	4:04:37 AM	Jock McPherson	Hard	0.8	Backed into conveyor system and bent structure. Conveyor shut down for four hours for repair.
<i>Don Sabey</i>		09/24/2001	9:26:41 AM	Bob Wylie	Hard	0.8	Damaged hydraulics and bent racking in aisle #2. Truck required to go to maintenance for repair.
<i>Don Sabey</i>		09/24/2001	1:06:00 PM	Bob Wylie	Soft	0.3	Bent guard rails at entrance to aisle #12. Rails need to be replaced. Driver warned to be more careful when entering aisles and to slow down in turns.
<i>Don Sabey</i>		09/25/2001	10:34:27 PM	Jock McPherson	Hard	0.8	Ran into racking in aisle #24. Rack bent and needs repairing. No visible damage to order picker.
<b>3</b>	<b>Reach Truck #12</b>						
<b>12</b>	<b>Toyota Counterbalance #47</b>						
<i>Joe Ferguson</i>		09/20/2001	9:27:36 AM	Frank Finn	Hard	0.8	Backed the reach truck into rack in aisle # 8. Guard rail bent ,, rack upright also bent. No apparent damages to reach truck.
<i>Don Sabey</i>		09/25/2001	1:49:02 AM	Bob Wylie	Hard	0.8	Don backed into stack of pallets and knocked them over. 12 pallets smashed beyond repair. Driver warned to keep his head up.
<b>13</b>	<b>Yale Reach Truck #32</b>						
<i>Andy McTavish</i>		09/21/2001	12:09:51 PM	Don Wilson	Soft	0.3	Turned corner too fast causing alarm. Driver warned to slow down as excessive speed coming out of aisles is extremely dangerous.

# Impacts by Vehicle

Date: 10/16/2002

Time: 1:30 PM

Page: 4

<b>Vehicle Auth.</b>	<b>Vehicle</b>				
Impact Date	Impact Time	Operator Name	Impact Type	Threshold	Description
<i>Supervisor</i>					
09/21/2001	4:24:48 PM	Alec Balfour	Soft	0.3	Driver just back to work after being retrained. Driver ran into reach truck # 40 and bent the forks on the pallet jack. Driver terminated. Untrainable
<i>Ralph Young</i>					
09/24/2001	4:03:53 AM	Guy LaFleur	Hard	0.8	Bent racking in aisle #11 on third level. Product removed from damaged rack until repaired. Driver sent for drug test.
<i>Don Sabey</i>					

**End Of Report**